





- Site Boundary
- Main Development Area
- Site Infrastructure
 - Met Mast Hardstanding
 - Control Building and Substation
 - BESS Site
 - Borrow Pit Search Area
 - Cranepad and Laydown
 - Temporary Compound
 - Access Track
- Phase 1 Habitat Classification
 - A1.2.2 - Coniferous woodland - plantation
 - A1.3.2 - Mixed woodland - plantation
 - B1.1 - Acid grassland - unimproved
 - B1.1/E1.6.1
 - B1.2 - Acid grassland - semi-improved
 - D1.1 - Dry dwarf shrub heath - acid
 - D2 - Wet dwarf shrub heath
 - E1.6.1 - Blanket sphagnum bog
 - E1.7 - Wet modified bog
 - E1.8 - Dry modified bog
 - E2.1 - Flush and spring - acid/neutral flush
 - E4 - Peat - bare
 - G1 - Standing water
 - G1.3 - Standing water - oligotrophic
 - G1.4 - Standing Water: Dystrophic
 - I1.2.1 - Scree - acid/neutral
 - I1.4.1 - Other exposure - acid/neutral
 - J4 - Bare ground




SCALE: See Scale Bar
SIZE: A3
PROJECT: 0730493
DATE: 06/11/2025


VERSION: A01
DRAWN: JS
CHECKED: ST
APPROVED: RP

Figure 8.2a
Phase 1 Habitat Survey Results
Creachan Wind Farm





- Site Boundary**
- Site Infrastructure**
- Borrow Pit Search Area
 - Temporary Compound
 - Access Track
- Phase 1 Habitat Classification**
- A1.1.1 - Broadleaved woodland - semi-natural
 - A1.2.2 - Coniferous woodland - plantation
 - B1.2 - Acid grassland - semi-improved
 - B5 - Marsh/marshy grassland
 - D1.1 - Dry dwarf shrub heath - acid
 - E2.1 - Flush and spring - acid/neutral flush
 - G1 - Standing water
 - J3.6 - Buildings
 - J4 - Bare ground



SCALE: See Scale Bar	VERSION: A01
SIZE: A3	DRAWN: JS
PROJECT: 0730493	CHECKED: ST
DATE: 06/11/2025	APPROVED: RP

Figure 8.2a
Phase 1 Habitat Survey Results
Creachan Wind Farm

